


12 Floor Plan MLA Offices

12.1 MLA Offices Ground Floor



SCALE B

1: 100 for A1 sheet
1: 200 for A3 sheet

DO NOT SCREW OFF THIS COVER/SCREW OFF AGAIN TO GET IT RECOMMENDED TO

1000

21 251

Amend

1

Sub A5

CHRYSLER DIF

Date	SEPT '88
------	----------

Sheet 13 OF 13

GROUND FLOOR FURNITURE PLAN

**Proposed Commercial Development
at Lot 520, Payanta Place,
NIGHTCLIFF, for Randall Olsen**

FAX: (08) 49 48 1812

1-800-691-8945 2717

© 1998 John Wiley & Sons, Inc.

PH: [03] 48 4507

000000

100% COTTON


100


2. Confidential


Member of Building Tradesmen Association of Montreal Territory

13 Building Asbestos Audit Register (MLA Offices)

13.1 Asbestos Audit Inspection (Asset No: MLA-NF)


Asset No:	MLA-NF	
Internal/External	Internal	
Level	Ground	
Location	Room 1- MLA Office	
Element	Ceiling/Walls/Floor	
Sample No:	-	
Asbestos Type	No Asbestos Detected	
Friability	-	
Condition	-	
Warning Signs Installed	-	Risk Rating
Recommendation	No Further Action Required	NIL


Asset No:	MLA-NF	
Internal/External	Internal	
Level	Ground	
Location	Room 2- Passage	
Element	Ceiling/Walls/Floor	
Sample No:	-	
Asbestos Type	No Asbestos Detected	
Friability	-	
Condition	-	
Warning Signs Installed	-	Risk Rating
Recommendation	No Further Action Required	NIL

Asset No:	MLA-NF	
Internal/External	Internal	
Level	Ground	
Location	Room 3- File Store	
Element	Ceiling/Walls/Floor	
Sample No:	-	
Asbestos Type	No Asbestos Detected	
Friability	-	
Condition	-	
Warning Signs Installed	-	Risk Rating
Recommendation	No Further Action Required	NIL

Asset No:	MLA-NF	
Internal/External	Internal	
Level	Ground	
Location	Room 4- Photo Copy	
Element	Ceiling/Walls/Floor	
Sample No:	-	
Asbestos Type	No Asbestos Detected	
Friability	-	
Condition	-	
Warning Signs Installed	-	Risk Rating
Recommendation	No Further Action Required	NIL

13.2 Asbestos Audit Inspection (Asset No: MLA-NF)


Asset No:	MLA-NF	
Internal/External	Internal	
Level	Ground	
Location	Room 1- MLA Office	
Element	Ceiling/Walls/Floor	
Sample No:	-	
Asbestos Type	No Asbestos Detected	
Friability	-	
Condition	-	Risk Rating
Warning Signs Installed	-	NIL
Recommendation	No Further Action Required	

Asset No:	MLA-NF	
Internal/External	Internal	
Level	Ground	
Location	Room 2- Passage	
Element	Ceiling/Walls/Floor	
Sample No:	-	
Asbestos Type	No Asbestos Detected	
Friability	-	
Condition	-	Risk Rating
Warning Signs Installed	-	NIL
Recommendation	No Further Action Required	


Asset No:	MLA-NF	
Internal/External	Internal	
Level	Ground	
Location	Room 3- File Store	
Element	Ceiling/Walls/Floor	
Sample No:	-	
Asbestos Type	No Asbestos Detected	
Friability	-	
Condition	-	Risk Rating
Warning Signs Installed	-	NIL
Recommendation	No Further Action Required	

Asset No:	MLA-NF	
Internal/External	Internal	
Level	Ground	
Location	Room 4- Photo Copy	
Element	Ceiling/Walls/Floor	
Sample No:	-	
Asbestos Type	No Asbestos Detected	
Friability	-	
Condition	-	Risk Rating
Warning Signs Installed	-	NIL
Recommendation	No Further Action Required	

13.3 Asbestos Audit Inspection (Asset No: MLA-NF)

Asset No:	MLA-NF	
Internal/External	Internal	
Level	Ground	
Location	Room 5-Kitchen	
Element	Ceiling/Walls/Floor	
Sample No:	-	
Asbestos Type	No Asbestos Detected	
Friability	-	Risk Rating
Condition	-	
Warning Signs Installed	-	
Recommendation	No Further Action Required	NIL

Asset No:	MLA-NF	
Internal/External	Internal	
Level	Ground	
Location	Room 6-Baby Change Area	
Element	Ceiling/Walls/Floor	
Sample No:	-	
Asbestos Type	No Asbestos Detected	
Friability	-	Risk Rating
Condition	-	
Warning Signs Installed	-	
Recommendation	No Further Action Required	NIL


Asset No:	MLA-NF	
Internal/External	Internal	
Level	Ground	
Location	Room 7- Bathroom	
Element	Ceiling/Walls/Floor	
Sample No:	-	
Asbestos Type	No Asbestos Detected	
Friability	-	Risk Rating
Condition	-	
Warning Signs Installed	-	
Recommendation	No Further Action Required	NIL

Asset No:	MLA-NF	
Internal/External	Internal	
Level	Ground	
Location	Room 8- Community Room	
Element	Ceiling/Walls/Floor	
Sample No:	-	
Asbestos Type	No Asbestos Detected	
Friability	-	Risk Rating
Condition	-	
Warning Signs Installed	-	
Recommendation	No Further Action Required	NIL

13.4 Asbestos Audit Inspection (Asset No: MLA-NF)

Asset No:	MLA-NF	
Internal/External	Internal	
Level	Ground	
Location	Room 9-Foyer	
Element	Ceiling/Walls/Floor	
Sample No:	-	
Asbestos Type	No Asbestos Detected	
Friability	-	
Condition	-	
Warning Signs Installed	-	
Recommendation	No Further Action Required	
		Risk Rating
		NIL

Asset No:	MLA-NF	
Internal/External	Internal	
Level	Ground	
Location	Room 10-Reception	
Element	Ceiling/Walls/Floor	
Sample No:	-	
Asbestos Type	No Asbestos Detected	
Friability	-	
Condition	-	
Warning Signs Installed	-	
Recommendation	No Further Action Required	
		Risk Rating
		NIL

Asset No:	MLA-NF	
Internal/External	External	
Level	Ground	
Location	Elevations	
Element	Walls	
Sample No:	-	
Asbestos Type	No Asbestos Detected	
Friability	-	
Condition	-	
Warning Signs Installed	-	
Recommendation	No Further Action Required	
		Risk Rating
		NIL