


14 Floor Plan Smith Family


14.1 Smith Family Offices Level 1



15 Building Asbestos Audit Register (Smith Family Offices)**15.1 Asbestos Audit Inspection (Asset No: Smith Family)**


Asset No:	S-F	
Internal/External	Internal	
Level	1	
Location	Room 1- Passage/Foyer	
Element	Ceiling/Walls/Floor	
Sample No:	-	
Asbestos Type	No Asbestos Detected	
Friability	-	
Condition	-	Risk Rating
Warning Signs Installed	-	NIL
Recommendation	No Further Action Required	

Asset No:	S-F	
Internal/External	Internal	
Level	1	
Location	Room 2 - Toilet	
Element	Ceiling/Walls/Floor	
Sample No:	-	
Asbestos Type	No Asbestos Detected	
Friability	-	
Condition	-	Risk Rating
Warning Signs Installed	-	NIL
Recommendation	No Further Action Required	


Asset No:	S-F	
Internal/External	Internal	
Level	1	
Location	Room 3 - Toilet	
Element	Ceiling/Walls/Floor	
Sample No:	-	
Asbestos Type	No Asbestos Detected	
Friability	-	
Condition	-	Risk Rating
Warning Signs Installed	-	NIL
Recommendation	No Further Action Required	


Asset No:	S-F	
Internal/External	Internal	
Level	1	
Location	Room 4 - Passage	
Element	Ceiling/Walls/Floor	
Sample No:	-	
Asbestos Type	No Asbestos Detected	
Friability	-	
Condition	-	Risk Rating
Warning Signs Installed	-	NIL
Recommendation	No Further Action Required	

15.2 Asbestos Audit Inspection (Asset No: Smith Family)

Asset No:	S-F	
Internal/External	Internal	
Level	1	
Location	Room 5 - Kitchen	
Element	Ceiling/Walls/Floor	
Sample No:	-	
Asbestos Type	No Asbestos Detected	
Friability	-	Risk Rating
Condition	-	
Warning Signs Installed	-	
Recommendation	No Further Action Required	NIL

Asset No:	S-F	
Internal/External	Internal	
Level	1	
Location	Room 6 - Boardroom	
Element	Ceiling/Walls/Floor	
Sample No:	-	
Asbestos Type	No Asbestos Detected	
Friability	-	Risk Rating
Condition	-	
Warning Signs Installed	-	
Recommendation	No Further Action Required	NIL


Asset No:	S-F	
Internal/External	Internal	
Level	1	
Location	Room 7 – Open Plan Offices	
Element	Ceiling/Walls/Floor	
Sample No:	-	
Asbestos Type	No Asbestos Detected	
Friability	-	Risk Rating
Condition	-	
Warning Signs Installed	-	
Recommendation	No Further Action Required	NIL

Asset No:	S-F	
Internal/External	Internal	
Level	1	
Location	Room 8 – Office	
Element	Ceiling/Walls/Floor	
Sample No:	-	
Asbestos Type	No Asbestos Detected	
Friability	-	Risk Rating
Condition	-	
Warning Signs Installed	-	
Recommendation	No Further Action Required	NIL

15.3 Asbestos Audit Inspection (Asset No: Smith Family)

Asset No:	S-F	
Internal/External	Internal	
Level	1	
Location	Room 9 – Stationary Store	
Element	Ceiling/Walls/Floor	
Sample No:	-	
Asbestos Type	No Asbestos Detected	
Friability	-	Risk Rating
Condition	-	
Warning Signs Installed	-	
Recommendation	No Further Action Required	NIL

Asset No:	S-F	
Internal/External	Internal	
Level	1	
Location	Room 10 - Store	
Element	Ceiling/Walls/Floor	
Sample No:	-	
Asbestos Type	No Asbestos Detected	
Friability	-	Risk Rating
Condition	-	
Warning Signs Installed	-	
Recommendation	No Further Action Required	NIL

Asset No:	S-F	
Internal/External	External	
Level	1	
Location	Verandah	
Element	Ceiling/Walls/Floor	
Sample No:	-	
Asbestos Type	No Asbestos Detected	
Friability	-	Risk Rating
Condition	-	
Warning Signs Installed	-	
Recommendation	No Further Action Required	NIL

Asset No:	S-F	
Internal/External	External	
Level	1	
Location	Elevations	
Element	Roof/Facia/Walls	
Sample No:	-	
Asbestos Type	No Asbestos Detected	
Friability	-	Risk Rating
Condition	-	
Warning Signs Installed	-	
Recommendation	No Further Action Required	NIL